

21 July 2021



General Motors Vehicles Supported by GDS2 or Tech2/Tech2Win

General Motors states that the method to correctly identify vehicle diagnostic trouble codes (DTCs) is by using the appropriate GM diagnostic software: GDS2 or Tech 2/Tech2Win, each of which can scan a vehicle for all DTCs in one operation.

GM diagnostic software is supported by one of the GM approved diagnostic scan tools

- MDI or a J2534 device.

GM does not recommend the use of other scan tools and cannot guarantee their accuracy.

GM Tools Supplier:

To purchase the above GM Scan Tools please contact

Bosch Automotive Service Solutions
1555 Centre Road,
Clayton, Victoria Australia 3168
Phone: 1300 783 031
Fax: (03) 9541 6138
Email: customerservice.au@service-solutions.com

Subscription options for GM diagnostic software and more information on GM diagnostic tools can be found at:

www.acdelcotds.com

GMSi is the factory source for all diagnostic and repair procedures, wiring diagrams and associated repair information.

GM Service Programming System (SPS) is the ECU programming application that provides calibration updates and guided learn procedures where required.

Any repairs performed without using Genuine GM Parts and not following published GM collision repair procedures may result in erroneous DTCs and expose vehicle owners and occupants to unnecessary risk.

GM collision repair information can be accessed through GMSi or by subscription to www.acdelcotds.com



Below is the list of GM vehicles that are supported by GDS2 or Tech2/Tech2Win applications for DTC identification.

Model Year:	Support:	Vehicles:
Pre 1997	Tech 1	Where Datalink connector (DLC) exists
1997 – 2009	Tech2 / Tech2Win	Where Datalink connector (DLC) exists
2010	GDS2	Barina Spark Cruze
	Tech2 / Tech2Win	All other
2011	GDS2	Barina Spark Captiva 5 & 7 Cruze
	Tech2 / Tech2Win	All other
2012	GDS2	Barina Barina Spark Captiva 5 & 7 Colorado Cruze Malibu
	Tech2 / Tech2Win	All other
2013	GDS2	Barina Barina Spark Captiva 5 & 7 Colorado Colorado 7 Cruze Malibu Trax Volt
	Tech2 / Tech2Win	All other
2014 –	GDS2	All
	Tech2 / Tech2Win	–

Further details specifically available for each applicable vehicle model – please refer to GM Service Information Document ID # 5525750 – Collision Repair Position Statements.

Available online at : www.gmtradeparts.com.au